


HAZARDOUS ACCORDING TO WORKSAFE AUSTRALIA

MANUFACTURED BY:

AMERICAN INTERNATIONAL INDUSTRIES

2220 GASPAR AVENUE

LOS ANGELES, CA 90040



MATERIAL SAFETY DATA SHEET

PRODUCT NAME: IBD Builder Gel - Pink

DATE: 9/14/2004

REV. NEW

Section 1. Material Identification and Information

Hazardous Ingredients:

Component	CAS #	%	TOXICOLOGICAL DATA
Acrylated Oligomer	N/A	50-100%	None Established
Hydroxypropyl Methacrylate	27813-02-1	10-20%	None Established

Section 2. Physical / Chemical Characteristics

Boiling Point:	N/A	Specific Gravity:	Approx. 1
Vapor Pressure: (mm Hg and Temperature)	Not Available		(@ 25°C)
Vapor Density: (Air = 1)	Not Available	Melting Point:	N/A
Solubility in Water:	Insoluble	Evaporation Rate:	Negligible
Appearance:	Thick Viscous Liquid	Water Reactive:	No
Odor:	Faint		

Section 3. Fire and Explosion Hazard Data

Flash Point:	> 150°C
Auto-Ignition Temperature:	N/A
Flammability Limits in Air % by Volume:	LEL: N/A UEL: N/A
Extinguisher Media:	Carbon dioxide, dry chemical, or foam.
Special Fire Fighting Procedures:	Cool exposed containers with water spray. Use self-contained breathing apparatus in confined areas.
Unusual Fire and Explosion Hazards:	Product may polymerize at high temperatures. Polymerization is an exothermic reaction and may produce sufficient heat to cause decomposition and/or rupture containers.

Section 4. Reactivity Hazard Data


Stability:	<input checked="" type="checkbox"/> Stable	<input type="checkbox"/> Unstable
Conditions to Avoid:	Polymerization may occur at high temperatures.	
Incompatibility (Materials to Avoid):	Direct heat, sunlight, primary and secondary amines, acids and alkalis.	

HAZARDOUS ACCORDING TO WORKSAFE AUSTRALIA

MANUFACTURED BY:

AMERICAN INTERNATIONAL INDUSTRIES

2220 GASPAR AVENUE
LOS ANGELES, CA 90040



MATERIAL SAFETY DATA SHEET

PRODUCT NAME: IBD Builder Gel - Pink **DATE:** 9/14/2004
REV. NEW

Hazardous Polymerization:

May Occur Will Not Occur

Section 5. Health Hazard Data

Primary Routes of Entry: Inhalation Skin Absorption Ingestion Eye Contact
Carcinogen Listed In: NTP IARC Monograph OSHA Not Listed

Health Hazards: Acute: May cause skin irritation in certain individuals. Eye Contact: May be irritating.
Chronic: May cause dermal sensitization in certain individuals.

Signs and Symptoms of Exposure:

Redness, itching or swelling of skin. May cause eye irritation.

Medical Conditions Generally Aggravated by Exposure:

None known.

Emergency First Aid Procedures:

Eye Contact: Thoroughly flush eyes with water. Contact a physician.
Skin Contact: Remove contaminated clothing, wash with soap and water. Contact a physician.
Inhalation: Not applicable.
Ingestion: Do not induce vomiting. Seek medical attention.

Section 6. Control and Protective Measures

Respiratory Protections (Specific Type):

Not required with normal use.

Protective Gloves: Recommended for sensitive skin.

Eye Protection: Safety goggles.

Ventilation to be Used: Local Exhaust Other (Specify)

Other Protective Clothing and Equipment:

None

Hygienic Work Practices: Good Manufacturing Practices.

Section 7. Precautions for Safe Handling and Use / Leak Procedures

Steps to be Taken if Material is Spilled or Released:

Soak up with inert absorbent material (sand, vermiculite). Flush area immediately with water. Prevent water from entering waterways.

Waste Disposal Methods: Use landfill or incinerate in accordance with applicable local, state, and federal regulations.


HAZARDOUS ACCORDING TO WORKSAFE AUSTRALIA

MANUFACTURED BY:

AMERICAN INTERNATIONAL INDUSTRIES

2220 GASPAR AVENUE

LOS ANGELES, CA 90040



MATERIAL SAFETY DATA SHEET

PRODUCT NAME: IBD Builder Gel - Pink

DATE: 9/14/2004

REV. NEW

Precautions to be taken in Handling and Storing:

Store in a cool, shaded, well ventilated, dry area away from direct heat and sunlight.

Other Precautions and/or Special Hazards:

None